DART AEROSPACE LTD	Work Order:	19537
Description: Long Step Assembly – High Skid, LH	Part Number:	704A 41 640 008
D350-591-211		
Dwg: D3070 Rev. A1	Qty:	10
RF 02.11.13		Page 1 of 2

Step	Location	Procedure	Bv	Date	044
1	DC	Issue Traveller	1 N	Date	Qty
		Dwg not required	1	03.08.27	10
2	DC	Photocopy bluefile and type labels per PPP 704A 41 640 008 GHG001 CHGCOZ WL 45	d)	04.03.12	10
3	GA	Cut D2622-120C extrusion to 116.25" long as per Dwg D3070	10	10 100	† <u></u> -
		using cutting table setup DT 8185-2A			
		Pick: Qty Part Number Description Batch	/		
	\	1 D2622-120C Extrusion B 18809	1	04-03-08	10
		Ensure wall thickness is 0.070 to 0.090	pnu	03-03-08	
4	GA _.	Drill extrusion per Dwg D3070 using Jig DT8680 for rivets.	mel	04-03-08	10
5	GA	Deburr	1		
	005		mil	04-03-08	10
6	QC5	Inspect work to Step 5	W	0.1.100	
7	WA	Bevel end for welding FWD ONLY	144	ntlostox	10
		Total and for Wolding I TID OILE	M	nuheho	10
8	WA	Weld Support using Jig DT8681, weld Fwd End Plate per QSI	2	VI/UJUS	10
41		004 & Dwg D3070		•	
		Pick:	AA	1 / 1 / 2	_
	\	Qty Part Number Description Batch 1 D3063-1 Support D17830 R9555		04/03/08	
		1 D3063-1 Support D19830/8/9555 1 D3067-1 End Plate R19558	12/2	1107	$ I \cup I $
		A/R Aluminum Rod M13066			
9	GA ·	Grind End Plate flush	/)		
10	QC9 & 5	Inspect weld and work to Step 9	ml	04-03-12	10
	40000	moposi word and work to otep 5	no	04/03/17	16
11	FP	Chemical conversion coat as per QSI 005 4.1	00	0103-19	
12	GA	Assemble Leg Assembly as per Dwg D3070. D3066-1 are done Pick: with Step Leg Assy, don't add to the Box. It os on is		0.024	
		Qty Part Number Description Batch			
	V	1 D3065-041 Step Leg Assy <u>B 19557</u>			
		2 D3066-1 Spacer <u>B19557</u> 16 MS20600AD4W4 Rivet <u>M13747</u>	1	2	
	`	16 MS20600AD4W4 Rivet M13767	ml	04-03-22	10
13	QC5	Inspect work to step 12	Ã		181
			10	04.03.22	10
14	WA	Bevel Aft end for welding		, ,	
45	14/4		IN	04/03/22	/c
15	WA	Inspect for foreign object per QSI 024	MS	UC/183/22	10
16	WA	Weld Aft End Plate per QSI 004 & Dwg D3070	7-9-5	ع ارماا	
		Pick:			
		Qty Part Number Description Batch			
	, \	1 D3067-1 End Plate \$1953 8	an	114/2/-	10
	DDA	A/R Aluminum Rod M/3672	7-75	07/03/22	, 0
1	00 U	7-03-25 XX CANCEL PEDS. 41.16	(CTA)A PROMISE	N ages at ass.	LONG TOP
		UNDER REVIEW	DF	LEAS	EN
	.4.	33.06.06 PW	no	2/11/01 DF	JU
		V - 1/2 / 1/2	H H	, , , , , , , , , , , , , , , , , , ,	

Work Order:			WORK ORDER	CHANGES					
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Manuf / Design Mgr	Approval QC Inspector
							0		
NCR			WORK ORDER	NON-CONFOR	MANCE				
DATE	STEP	Description of NC section A		NON-CONFOR	MANCE Sign & Date		ication tion C	Approval Design Mgr	Approval QC Inspector
	STEP	Description of NC		Corrective Action	Sign &		ication tion C	Approval Design Mgr	Approval QC Inspector
DATE	STEP	Description of NC section A		Sorrective Action Section B	Sign &		ication tion C	Approval Design Mgr	Approval QC Inspector

	PAR#:	Fault Category:	DQA:	Date:
NOTE: Date & initial all entries H:Admin-QA\ISO\forms\w/oncB.doc			QA: N/C Closed:	_ Date:

DART AEROSPACE LTD	Work Order:	19537
Description: Long Step Assembly – High Skid, LH	Part Number:	704A 41 640 008
D350-591-211		,
Dwg: D3070 Rev. A1	Qty:	0
		Page 2 of 2

17	GA	Grind End Plate flush	SB	04/03/23	10
18	QC9 & 5	Inspect work to Step 17 – Check dimension 440.56" from Dwg D3070	16	X1 03 23	16
19	FP	Powder Coat Gloss White (Ref: 4.3.5.1) per QSI 005 4.3	1	04.03.24	16
20	FP	Wing Walk per Dwg D3070 and QSI 005 4.4	2	04.03. LY	10
21	QC3	Inspect Powder Coat and Wing Walk	M	o4.05.24	10
22	D3079.044 04.03.25	Pick: Packing Kit Qty Part Number Description Batch 4 D2182B035 Rubber Cushion B20434 8 D2274 Radius Block B20307 2 D2856-400-720 Abrasion Strip B9645 2 D3064-1 Clamp Clamp 4 D3080-1 Support Assy B20456 4 D3080-1 Clamp B01539 2 AN3-35A Bolt M13063 10 AN4-11A Bolt M13735 4 AN960JD10 Washer M13441 20 AN960JD416 Washer M4312 M13356 2 MS21042L3 Nut (or -3) M13376 10 MS21042L4 Nut (or -4) M13376	cf (1	૦૫/ <i>૦</i> ૩/૦૧	10
23	QC4	Inspect 100% Kit for Completeness on the W/O	PER	040325	10.
24	PK	Package for shipping as per PPP 704A 41 640 008	CP	0403-25	10
25	AC	Cost / part 22 1.91	540	4.03.29	10
26	DC	Close W/O z Z Y, f # Inspect Level 21	*	04.03.26	10

Rev	Date	Change	Revised By	Approved
Α	02.11.01	New issue	KJ R	di
AI	03.01.14	110.71" WAS 110.56" : Dwg Rev Al	林	-4-
A2	03.01.16	D3194-041 WAS D3079-041 ; CAGOOZ	THE PARTY NAMED IN COLUMN TO THE PARTY NAMED	d

UNDER REVIEW

CHNEEL RE 05 -1.16

RELEASED

Dart Aerospace Ltd

Work		W	ORK ORDER CHANGES					
Order:								
DATE STEP		PROCEDU	RE CHANGE	Ву	Date	Qty	Approval Manuf / Design Mgr	Approval QC Inspector
NCR	4	W	ORK ORDER NON-CONFOR	MANCE				
DATE	STEP	Description of NC section A	Corrective Action Section B Intial	Sign & Date	Verifi Sec	cation tion C	Approval Design Mgr	Approval QC Inspector
		4						
<u>.</u> .								
		PAR#:	Fault Category:	DQ/	A:		Date:	
				OA: N/C CI	ocod:		Date:	

NOTE: Date & initial all entries H:Admin-QA\ISO\forms\w/oncB.doc

QA: N/C Closed:

Job Costing Report

Dart Aerospace Ltd. Hawkesbury

Aug 27, 2003 02:05 pm

0.000%

Work Order No : 0019537

Project Name : *704A 41 640 008 Department Code:

Project For : WK347 Burden Flags : NNNNNNN Work Order Type : Main WO Status : Open

Main WO Number : Invoice State : Not Invoiced

House Part Number: *704A 41 640 008 Invoice Date

Description : Heli-Access-Step, Long LH Invoice Number :

Manufactured: Yes Invoice Amount: 0.00
Amount Req'd: 10

Amount Done : 0 Order Entry No :

Start Date : 08-27-03 OE Value : 0.00

Est Finish Date : 11-28-03
Act Finish Date : Est Margin : 0.000%

Drawings Reqd : No Ok for Approval :

Approval Rec'd : \$0 Posted to Finished Goods

Actual Margin :

=======================================		Estimated	Actual	Var. %		Posted	To Post
Material Cost	:	0.00	0.00	0.00	====	0.00	0.00
Engineering Hours	:	0.00	0.00	0.00			
Engineering Cost	:	0.00	0.00	0.00		0.00	0.00
Production Hours	:	0.00	0.00	0.00			
Production Cost	:	0.00	0.00	0.00		0.00	0.00
Testing Hours	:	0.00	0.00	0.00	4.1		
Testing Cost	:	0.00	0.00	0.00		0.00	0.00
OverHead Hours	:	0.00	0.00	0.00			
OverHead Cost	:	0.00	0.00	0.00		0.00	0.00
SubContract Hours	:	0.00	0.00	0.00			
SubContract	:	0.00	0.00	0.00		0.00	0.00
Misc. Hours	:	0.00	0.00	0.00			
Misc.	:	0.00	0.00	0.00		0.00	0.00
		========	_========	======			
Burden	:	0.00	0.00	0.00			
		========	========	======			
Total Cost	:	0.00	0.00	0.00			
Margin	:	0.000	0.000				
Selling Cost	:	0.00	0.00				

		Estimated	Actual
Labour Hrs/Amount Done	:	0.00	0.00
Profits/(Loss)	:	0.00	0.00